

Cost Comparison – Fleet Manager

Remove and Replace Turbocharger on E5368

Outside vendor Parts: \$8,250

Labor: \$1,188 (6hrs.x \$198/hr.)

Downtime: 2+ weeks minimum.

TOTAL: \$9,438.00

Amador Fire Parts: \$7,203.87

Labor: \$248 (4hrs.x \$62/hr.)

Downtime: 4-6 hours

TOTAL: \$7,451.87

Major Service including Midship Pump Repair on E5361

Outside vendor Parts: \$3,742.88

Labor: \$14,256 (72hrs.x \$198/hr.) (40hrs. For pump repair)

Downtime: 6 weeks min.

TOTAL: \$17,998.88

Amador Fire Parts: \$2,495.25

Labor: \$1,984 (32hrs.x \$62/hr.) (12hrs. For pump repair)

Downtime: less than one work week

TOTAL: \$4,479.25

NOTE:

Parts for “outside vendors” were given a retail + 25% markup which was the average.

Amador Fire receives list price or lower on filters, parts and commodities.

\$198/hr. Was the average shop rate.